

TOOL MODEL: MXTP-05

PRESSURE/TORQUE CONVERSION CHART

Standard Torque Chart

1500 812 112 1101 1 1600 867 120 1175 1 1800 977 135 1324 1 2000 1087 150 1474 1 2200 1198 166 1623 1 2400 1308 181 1773 1 2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	54R 04 110 124 38 52 65 79 93 207 220 234 248 262 276
1600 867 120 1175 1 1800 977 135 1324 1 2000 1087 150 1474 1 2200 1198 166 1623 1 2400 1308 181 1773 1 2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	110 124 38 52 65 79 93 207 220 234 248 262
1800 977 135 1324 1 2000 1087 150 1474 1 2200 1198 166 1623 1 2400 1308 181 1773 1 2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	24 38 52 65 79 93 207 220 234 248 262
2000 1087 150 1474 1 2200 1198 166 1623 1 2400 1308 181 1773 1 2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	38 52 65 79 93 207 220 234 248 262
2200 1198 166 1623 1 2400 1308 181 1773 1 2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	52 65 79 93 207 220 234 248 262
2400 1308 181 1773 1 2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	65 79 93 207 220 234 248 262
2600 1419 196 1923 1 2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	79 193 207 220 234 248 262
2800 1529 212 2073 1 3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	93 207 220 234 248 262
3000 1640 227 2223 2 3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	207 220 234 248 262
3200 1751 242 2373 2 3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	220 234 248 262
3400 1861 257 2523 2 3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	234 248 262
3600 1972 273 2673 2 3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	248 262
3800 2082 288 2823 2 4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	262
4000 2193 303 2973 2 4200 2304 319 3123 2 4400 2415 334 3273 3	
4200 2304 319 3123 2 4400 2415 334 3273 3	276
4400 2415 334 3273 3	
	290
4600 2525 349 3423 3	303
	317
4800 2636 365 3574 3	31
5000 2747 380 3724 3	345
5200 2857 395 3873 3	358
5400 2967 410 4023 3	372
5600 3078 426 4172 3	386
5800 3188 441 4321 4	100
6000 3298 456 4471 4	14
6200 3408 471 4619 4	27
6400 3517 486 4768 4	l 4 1
6600 3627 502 4916 4	155
6800 3736 517 5065 4	168
7000 3846 532 5214 4	182
7200 3953 547 5359 4	ŀ96
	510
	524
	538
	552
	65
	579
	593
	607
	620
	634
	648
	662
	676
	690

IMPORTANT SAFETY INSTRUCTIONS

WARNING: Your **HYTORC TORQUE MACHINE** is a power tool, and as with any power tool, certain safety precautions should be observed to avoid accidents or personal injury. The following tips will assist you.

- READ ALL INSTUCTIONS.
- KEEP WORK AREA CLEAN AND WELL LIT.
- CONSIDER WORK AREA ENVIRONMENT. Electrical Pumps should never be used in an atmosphere which can be considered potentially volatile. If there is any doubt, use an air pump. Also Note: metal to metal contact can cause sparks, precautions should be taken.
- AVOID PREMATURE TOOL STARTING. The Pump Remote Control is for the TOOL OPERATOR only.
- STAY CLEAR DURING OPERATION. In most cases, the tool will allow "hands free" operation. If the tool must be held or steadied during operation, use alternative means of securing the tool to the application
- GUARD AGAINS ELECTRIC SHOCK. Ensure the pump is properly grounded and the proper voltage is being used.
- STORE IDLE TOOLS. When not in use, tool sand accessories should be properly stored to avoid deterioration
- USE RIGHT TOOL. Don't force small tools or attachments to do the job of a larger tool. Don't use a tool for purposes not intended.
- **PROPER SAFETY ATTIRE.** When handling/operating hydraulic equipment use work gloves, hard hats, safety shoes and other applicable clothing.
- USE SAFETY GLASSES.
- **MOVING EQUIPMENT.** Do not use hydraulic hoses, uni-swivels, pump power or remote cords as means of moving the equipment.
- MAINTAIN TOOLS WITH CARE. For top performance, inspect tools, powerpack and accessories for visual damage frequently and always prior to use. Always follow instruction for proper tool and pump maintenance. Refer to the Operations Maintenance Section for further clarification
- STAY ALERT. Watch what you are doing. Use Common sense. Do not use power equipment under the influence of any mood altering substances.

PRIOR TO OPERATION

- Ensure that all hydraulic connections are securely connected and there is no leakage
- Verify that the Hydraulic hoses are not kinked or otherwise damaged.
- Ensure the square drive and its retainer are fully and securely engaged.
- Be certain that all connectors, elbows, fitting and swivels are not bent, loose or damaged.

PRIOR TO USE.

- Check sockets for size, quality and flaws. (Do not use if questionable)
- Cycle tool to ensure proper function.
- Locate a solid, secure reaction point.
- Be sure the reaction arm retaining clamp is fully engaged.
- Be sure the hydraulic hoses are free of the reaction point.
- Pressurize the system momentarily; if the tool tends to "ride up" or to "creep", stop and re-adjust the reaction arm to a more solid and secure position.

NOTE: Remain clear of the reaction arm during operation and never put body parts between reaction arm and reaction surfaces.

- ALWAYS USE QUALITY ACCESSORIES. Always use top quality impact sockets in good condition which are
 the correct size and fully engage the nut. Hidden flaws, however, remain a possibility which could cause
 breakage, so stay clear of sockets during operation
- DO NOR USE other equipment to enhance performance (Hammer on Socket/Tool)NOTE: Hytorc Pumps are
 designed to operate Hytorc Tools only. Damage may occur to the pump or the product that is being operated
 due to misuse.

SAVE THESE INSTRUCTIONS FOR FUTURE USE!